



COUPLE6 ALIGNMENT REPORT



REPORT ISSUED BY:


9 Mechanics co.,ltd
1/99 moo12 Bangpheeayai Bangphee Samuthprakan
02-751-0755 , 086-667-8789

COMPANY / JOB INFORMATION

Machine Name MOTOR PUMP 160KW. PP3
Company Name Amita Thailand
Location
Address

City
State
Postal Code(ZIP)
Country
Notes

MACHINE SETUP



UNITS

OFFSET = mm, ANGLE = mm/100mm




TARGET INFORMATION

MODEL NUMBER :
Calib. Due : September 2018

Serial Number : 80-00256
FW REV. : 3.217

ALIGNMENT RESULTS

SIDE VIEW / VERT.



GAP


-0.04

RPM	TOLERANCES	
	ACCE...	EXCEL...
1200+		
OFFSET	0.10	0.06
ANGLE	0.08	0.05
GAP	0.13	0.08

OFFSET

0.02

TOP VIEW / HORIZ.



GAP

0.04


RPM	TOLERANCES	
	ACCE...	EXCEL...
1200+		
OFFSET	0.10	0.06
ANGLE	0.08	0.05
GAP	0.13	0.08

OFFSET

0.19

SOFT FOOT

FOOT	TIGHT	LOOSE	CHAN...	NOTES
1	---	---	---	N/A
2	---	---	---	N/A
3	---	---	---	N/A
4	---	---	---	N/A



REPEATABILITY

#	V Offset	V Gap	H Offset	H Gap	DATE	TIME	SPAN	#POINTS	MODE	METHOD
✓ 1	0.02	-0.04	0.19	0.04	4/15/2022	1:05 PM	311.7°	8	Coupled	Auto Clock

